

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	5.48	10/13/2014 10/13/2014	Herman Phillips

LM Start		Rating **	A	Issue No.	3		
LM End		Issue Type +	Ma	Location *	LS		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Operations & Maintenance Manuals				°		°
					°		°
DWR ID	DWR_RD2068_01_f_2014_3						
Action/Comments							
Inspector Comments: RD 2068 has the O&M Manual on hand.							

No Photos

LM Start		Rating **	A	Issue No.	4		
LM End		Issue Type +	Ma	Location *	LS		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Flood Preparedness & Training				°		°
					°		°
DWR ID	DWR_RD2068_01_f_2014_4						
Action/Comments							
Inspector Comments: RD 2068 crew members are trained yearly.							

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				°
					°
DWR ID	DWR_RD2068_01_f_2014_5				
Action/Comments					
Inspector Comments: RD 2068 has emergency supplies stored.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	5.48	10/13/2014 10/13/2014	Herman Phillips

LM Start	0.51	Rating **	A	Issue No.	1
LM End	5.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.401158 °	38.329087 °
				-121.693845 °	-121.694105 °
DWR ID	DWR_RD2068_01_f_2014_1				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Slopes has been burned and dragged.					

Photo 1 of 1 : FA_2014_RD2068_193_1_20141126_00001.jpg



Looking downstream from waterside slope RD 2068 Levee mile 0.51.

LM Start	2.91	Rating **	A	Issue No.	2
LM End	5.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.366488 °	38.329087 °
				-121.693953 °	-121.694105 °
DWR ID	DWR_RD2068_01_f_2014_2				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Landside slope looking downstream from levee mile 2.91 to 5.50. Slopes burned and dragged.					

No Photos

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Back Levee	Left	3.22	10/13/2014 10/13/2014	Herman Phillips

LM Start	0.00	Rating **	A	Issue No.	9
LM End	0.00	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.358608 °	38.358608 °
				-121.740390 °	-121.740390 °
DWR ID	DWR_RD2068_02_f_2014_9				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Looking downstream from landward levee slope slope was mowed.					

Photo 1 of 1 : FA_2014_RD2068_194_9_20141126_00004.jpg



Looking downstream from levee mile 0.00 along unit 2, 2068 at the landward levee slope.

LM Start	0.03	Rating **	C	Issue No.	67
LM End	0.80	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.358608 °	38.369834 °
				-121.740387 °	-121.740199 °
DWR ID	DWR_RD2068_02_s_2014_67				
Action/Comments					
Keep the crown roadway free of vegetation.					

No Photos

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement